






Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb /
 Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu

XX = AA

Position

- 1 = H 961 956 NU
- 2 = H 961 937 NU
- 3 = H 961 395 NU




SOFTMOOD


A 9134 .. + A 9135 .. + A 9136 .. + A 9137 ..

0811 / H 965 798 - 1
 (+ A 865 612)
 Made by JADO in E.U.


A 9136





A 9134



A 9137



A 9135



Ideal Standard International BVBA
 Chaussée de Wavre, 1789 - box 15
 1160 Bruxelles
 Belgium

www.idealstandardinternational.com



