





Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb /
 Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu

XX = AA

Position

- 1 = H 961 942 NU
- 2 = H 961 493 NU




CONNECT
 E 6985 ..



1104 / H 965 794
 (+ A 865 612)
 Made by JADO in E.U.


E 6985






1
↓
7


2




3




4



1



5




5b
5a

x3




6

x3



x3


7



2,5

2,5

2,5



E 6981

E 6981

E 6985